03161.001500 JUN 0 6 2007

PATENT

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent of:

DANIEL LAURENT

TC/Art Unit: 3611

Appln. No.: 10/732,000

Tochart Unit: 3611

Appln. No.: 10/732,000

Confirmation No. 5840

Filed: December 10, 2003

For: SYSTEM FOR STEERING A VEHICLE

HAVING A DEGRADED MODE IN

THE EVENT OF FAILURE OF A

WHEEL STEERING ACTUATOR

U.S. Patent No.: US 6,991,061 B2

Issued: January 31, 2006

June 5, 2007

Commissioner for Patents P.O. Box 1450 Alexandria, VA 22313-1450 Certificate
of Correction

CERTIFICATE OF CORRECTION UNDER RULES 322 AND 323

Sir:

It is respectfully requested that a Certificate of Correction be issued by the Patent and Trademark Office due to errors which appear in the printed patent as a result of Patent and Trademark Office mistakes, and mistakes of a clerical, typographical, or minor character, which were not the fault of the Patent and Trademark Office. A Certificate of Correction form is attached.

The Commissioner is authorized to charge any additional fees or credit any overpayment to Deposit Account No. 06-1205.

Patentee's undersigned attorney may be reached in our New York office by telephone at (212) 218-2100. All correspondence should continue to be directed to our address given below.

Respectfully submitted,

John D. Murnane

Registration No. 29,836

Lock See Yu-Jahnes Registration No. 38,667

Attorneys for Applicant

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza
New York, New York 10112-3801
Facsimile: (212) 218-2200

NY_Main 590818v1

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO.

US 6,991,061 B2

DATED

January 31, 2006

INVENTOR(S) :

DANIEL LAURENT

Page 1 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 4

Line 12, "1_{RL}" should read --1_{FL}--;

Line 64, "a1FL and a 1FR" should read -- \propto 1_{FL} and \propto 1_{FR}--; and

Line 64, "a1FL and a 1FR," should read -- \propto 1_{FL} and \propto 1_{FR},--.

COLUMN 7

Line 47, "steering" should read --steerable--;

Line 50, "3," should read --claim 3,--; and

Line 52, "a angle" should read --a steering angle--.

COLUMN 8

Line 42, "at" should read --a--; and

Line 62, "outside" should read --outside as--.

MAILING ADDRESS OF SENDER:

NY_Main 590818v1

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3801 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile

(212) 218-2200 - Facsimile
Form PTO 1050 (Rev. 3-82)

PATENT NO. US 6,991,061 B2

No. of add'l. copies @ 30¢ per page



UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO.

US 6,991,061 B2

DATED

January 31, 2006

INVENTOR(S) :

DANIEL LAURENT

Page 2 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 10

Line 8, "outside" should read --outside as--; and Line 49, "claim 1," should read --claim 2,--.

FCHS_WS 590818v1

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3801 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile PATENT NO. <u>US 6,991,061 B2</u>

No. of add'l. copies @ 30¢ per page

__> ___